Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA00445DE

This certificate, issued to

West Star Aviation, Inc. 796 Heritage Way Grand Junction, Colorado 81506-8643

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product—Type Certificate Number:

A28CE

Make:

Cessna Conquest

Model.

441

Description of the Type Design Change:

Installation of B/E Aeropsace Sweep-On 2000 Crew Oxygen Mask in accordance with West Star Aviation Inc. Master Drawing List Report No. 00-58057-MDL, Revision IR, dated May 5, 2000, or later FAA approved revisions.

Limitations and Conditions:

- FAA Approved Flight Manual Supplement, 00-58057-POHS, dated January 24, 2001 or later approved revision is
- Instructions for Continued Airworthiness as addressed in Section Ii and III of West Star Aviation, Inc. Installation Manual Report 35-10-02, Revision IR, dated May 1, 2000, or later FAA accepted revision is required for this installation.
- This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft.
- If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

May 1, 2000

Date reissued:

Date of issuance:

January 24, 2001

Date amended:

Ronald F. May (Signature), Manager

Northwest Mountain Region Denver Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.